

Filtered to show: issues.status = 'Active'

Issue 32: Wake Way, Speed limit signpost

Category	(1) Environment	Assigned To	Grangepark Clerk
Status	Active	Due Date	
Priority	(2) Normal	Opened By	Andy Millerchip
Attachments	📎(0)	Opened Date	30-Apr-18

Description

Wake Way Sign Post been damaged and is on the leen, Report to street doctor 30/04/2018.

Comments



Issue 33: Broken Bench outside the Chemist

Category	(1) Environment	Assigned To	Grangepark Clerk
Status	Active	Due Date	
Priority	(2) Normal	Opened By	Andy Millerchip
Attachments	📎(0)	Opened Date	30-Apr-18

Description

Bench broken outside Chemist , Management agency needs informing . Informed 30/04.2018

Comments



Issue 34: Cobbles lifted o the walk way by the chemist

Category	(1) Environment	Assigned To	Grangepark Clerk
Status	Active	Due Date	
Priority	(2) Normal	Opened By	
Attachments	📎(0)	Opened Date	30-Apr-18

Description

Management agency, Eddisons need informing 30/04/2018

Comments



Issue 38: Lark Lane /Junction with Quinton Road Yellow Bollards

Category	(1) Environment	Assigned To	Grangepark Clerk
Status	Active	Due Date	
Priority	(2) Normal	Opened By	
Attachments	📎(0)	Opened Date	30-Apr-18

Description

Missing Bollard , which may allowing vehcular access

Report to Highways 30/04/2018

Comments



Issue 42: Pergola by Woodland View Primary School

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	
Priority	(2) Normal	Opened By	Mark Wilson
Attachments	📎(0)	Opened Date	22-May-18

Description

Pergola by Woodland View School - quote needed for some trellis work tp be replaced

Comments

[Version: 10/07/2018 08:50:37] 09/07/2018 - Parish Council to decide how to proceed



Issue 45: Wire Fence at the bottom of Foxfields

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	
Priority	(2) Normal	Opened By	Andy Millerchip
Attachments	📎(0)	Opened Date	04-Jun-18

Description

To provide a quote for a wire fence at the bottom of Foxfields to prevent dogs from running through the hedge onto the road

Comments

[Version: 04/06/2018 11:41:03] Wire Fence at the bottom of Foxfields
[Version: 10/07/2018 08:51:55] Quote promised on 05/07/2018 but as yet not received 09/07/2018
[Version: 13/07/2018 11:19:31] Quote to be received by 17th July

Issue 46: Wild Flower areas - remedial action

Category	(1) Environment	Assigned To	Ken Francis	
Status	Active	Due Date		
Priority	(2) Normal	Opened By	Andy Millerchip	
Attachments	📎(0)	Opened Date		04-Jun-18

Description

on the buttercup side: cut down then remove waste - no further action

on the dock leaf side: cut down then remove waste then spray back

make a planned maintenance task for next year to spray back these areas after the weeds have germinated but before the flowers are apparent

re-rotavate and reseed the new wild flower area next to the bridleway

Comments

[Version: 10/07/2018 08:52:42] 09/07/2018 - Need strategy on how to proceed . To determine at meeting with Ken on Thursday 11th July 18
[Version: 13/07/2018 11:21:11] 12/07 Main three areas revert to year 1 process - spray, rotavate, spray and then seed in March . New area by the Pond try a different mix of perennial & grass

Issue 48: Timber Work

Category	(1) Environment	Assigned To	Ken Francis	
Status	Active	Due Date		30-Sep-18
Priority	(2) Normal	Opened By	Andy Millerchip	
Attachments	📎(0)	Opened Date		04-Jun-18

Description

All wooden benches and bridges to be steam cleaned then treated

Start with small bridge to prove the process

complete other bridges and all seating

Include the seating on the oval

include the seating in Wootton Brook Woods

Comments

[Version: 13/07/2018 11:22:24] 12/07 Waiting for the Equipment to be returned from another job. Works to be completed end of September

Issue 51: Baines Way - Overhanging trees

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	31-Jul-18
Priority	(2) Normal	Opened By	Andy Millerchip
Attachments	📎(0)	Opened Date	18-Jun-18

Description

Overhanging trees in Baines Way

Comments

[Version: 13/07/2018 11:23:30] Ken to schedule the works



Issue 56: Grass Area outside 9 the Saddlers

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	30-Sep-18
Priority	(2) Normal	Opened By	Andy Millerchip
Attachments	📎(0)	Opened Date	29-Jun-18

Description

Grass seeding needs doing in the Autum to a piece of land at 9 The Saddlers .

Visit was made in June but unable to complete the works due to the weather. Also agreed that their back hedge adjacent to Middle Headge would be put on the Maintenance schedule to be cut twice a year.

Comments

[Version: 13/07/2018 11:25:44] Works to be completed In September

Issue 58: Roundabout Near Junction to Holiday Inn and Amazon Warehouse

Category	(1) Environment	Assigned To	Northampton County Council
Status	Active	Due Date	05-Sep-18
Priority	(2) Normal	Opened By	Andy Millerchip
Attachments	📎(0)	Opened Date	04-Jul-18

Description

Tarmac separating creating potholes on two sections of the roundabout

Comments

[Version: 04/07/2018 14:03:40] Reported to Street Doctor 04/07/2018 - Incident Number 949423

[Version: 29/08/2018 10:41:28] will be done within 3 months - 5th Septe



Issue 62: Dead tree needs removin from the walkway of The Woodlands/Or the Spinney

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	30-Jul-18
Priority	(2) Normal	Opened By	Andy Millerchip
Attachments	📎(0)	Opened Date	04-Jul-18

Description

Dead Tree Needs removing

Comments

[Version: 04/07/2018 14:09:37] Reported to Ken 04/07/2018
[Version: 13/07/2018 11:28:24] Remove July and Replace in September



Issue 63: Highways Issues

Category	(1) Environment	Assigned To	Northampton County Council
Status	Active	Due Date	04-Nov-18
Priority	(2) Normal	Opened By	Mark Wilson
Attachments	📎(0)	Opened Date	09-Jul-18

Description

Loose Kerb stones at Cony Walk, The Oaks, Junction of Quintonside/Wake Way

Comments

[Version: 09/07/2018 13:01:53] Reported to the Street Doctor on 09/07/2018 ref: 949740

Issue 64: Highways Issues

Category	(1) Environment	Assigned To	Northampton County Council
Status	Active	Due Date	04-Nov-18
Priority	(2) Normal	Opened By	Mark Wilson
Attachments	📎(0)	Opened Date	09-Jul-18

Description

Loose Kerb Stones at Quintonside/Wake Way
School Lane - outside of the Community Centre loose block on left
Wake Way Near Badger Lane
Bridge Meadow Way missing Cobbles

Comments

[Version: 09/07/2018 13:03:45] Reported to street doctor on 09/07/2018 refL 949741

Issue 66: To receive Weekly Inspection Reports on Playgrounds

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	30-Jul-18
Priority	(2) Normal	Opened By	Andy Millerchip
Attachments	📎(0)	Opened Date	10-Jul-18

Description

To receive for information weekly inspection reports on playparks and equipment

Comments

[Version: 13/07/2018 11:29:17] to send copies of the weekly report to the Parish Clerk so that it can be circulated

Issue 67: Tree Works

Category	(1) Environment	Assigned To	Jon Hearn
Status	Active	Due Date	
Priority	(2) Normal	Opened By	Andy Millerchip
Attachments	📎(0)	Opened Date	10-Jul-18

Description

Tree Management Works as per attached Letter - July 2018

Comments

Issue 68: Deer Close - Far end the grass cutting has been missed

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	30-Jul-18
Priority	(2) Normal	Opened By	Mark Wilson
Attachments	📎(0)	Opened Date	10-Jul-18

Description

To determine who cuts this piece of land, photo attached - July 2018



Comments

[Version: 13/07/2018 11:30:07] Chris to Monitor and Check that he is able to Mow when it is next scheduled . Keep the Parish updated on progress

Issue 69: Harefield - Redundant ugly tree posts that needs removing

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	30-Jul-18
Priority	(2) Normal	Opened By	Mark Wilson
Attachments	📎(0)	Opened Date	10-Jul-18

Description

To determine if these works should be done by R&G - July 2018

Comments

[Version: 13/07/2018 11:30:39] Ken to remove



Issue 70: Deep Ruts in the Grass Verge at Cony Walk

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	
Priority	(2) Normal	Opened By	Mark Wilson
Attachments	📎(0)	Opened Date	10-Jul-18

Description

See attached photo - July 2018

Comments



Issue 71: Great Ground Walk- Fencing Missing

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	
Priority	(2) Normal	Opened By	Mark Wilson
Attachments	📎(0)	Opened Date	10-Jul-18

Description

See attached photo - July 2018

Comments



Issue 73: Poachers Close, Rotten collapsed fence

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	
Priority	(2) Normal	Opened By	Mark Wilson
Attachments	📎(0)	Opened Date	10-Jul-18

Description

See attached photo - July 2018

Comments



Issue 75: Brook View - Dead dangerous tree base is thin and Rotten

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	
Priority	(2) Normal	Opened By	Mark Wilson
Attachments	📎(0)	Opened Date	10-Jul-18

Description

See attached photo - July 2018

Comments



Issue 76: Bridge Meadow Way - 3 Low Fence posts missing

Category	(1) Environment	Assigned To	Ken Francis
Status	Active	Due Date	
Priority	(2) Normal	Opened By	Mark Wilson
Attachments	📎(0)	Opened Date	10-Jul-18

Description

See attached photo - July 2018

Comments



Issue 77: Bunding at Foxfields Country Park

Category	(1) Environment	Assigned To	Ken Francis	
Status	Active	Due Date		30-Sep-18
Priority	(2) Normal	Opened By	Andy Millerchip	
Attachments	📎(0)	Opened Date		13-Jul-18

Description

Comments

[Version: 13/07/2018 11:32:40] Ken need to keep the Council updated on progress

Issue 78: Foxfields Country Park - Deep Ruts

Category	(1) Environment	Assigned To	Ken Francis	
Status	Active	Due Date		30-Sep-18
Priority	(2) Normal	Opened By	Andy Millerchip	
Attachments	📎(0)	Opened Date		13-Jul-18

Description

Deep ruts to be flattened out by rotavating after it has been flailins in the 1st half of September . Typle 1 MOT to be rolled int the ground and gap to be seeded

Comments

Issue 81: End Of Finney Drive - Highway Issue

Category	(1) Environment	Assigned To	Northampton County Council	
Status	Active	Due Date		
Priority	(2) Normal	Opened By	Andy Millerchip	
Attachments	📎(0)	Opened Date		29-Aug-18


Description

End of Finney Drive - pothole where tarmac is separating

Reported to street doctor on 29/08/2018 reference number 953569

Comments



Category	(1) Environment	Assigned To	Ken Francis	
Status	Active	Due Date		
Priority	(2) Normal	Opened By	Andy Millerchip	
Attachments	 (0)	Opened Date		05-Sep-18

Description

Hedgerow needs cutting back off the fence (Bed no 932/13).

Comments